



臺南市天主教聖功女子高級中學 1070711水塔清洗

1




臺南市天主教聖功女子高級中學 1070711水塔清洗

2



聖功女中
養正樓水池

A photograph showing a dirty, brownish water tower interior. A white sign with black text is placed on a red plastic container in the center of the room. The floor is covered in a thick layer of brown sediment.



聖功女中
養正樓水池

A photograph showing the same water tower interior after cleaning. The floor is now clean and reflective, and the brown sediment has been removed. The white sign is still in the center.



中女紅盟
塔外土銀鑽公

A photograph showing a dirty water tower interior with white tiled walls and floor. A white sign with black text is placed on a red plastic container. The floor has some brown stains.






聖功女中
玄翰館土水塔

A photograph showing the same water tower interior after cleaning. The floor is now clean and reflective, and the brown stains have been removed. The white sign is still in the center.

臺南市天主教聖功女子高級中學 1070711水塔清洗

3



臺南市天主教聖功女子高級中學 1070711水塔清洗

4



臺南市天主教聖功女子高級中學 1070711水塔清洗

5

